ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
9

Ward Name
Vidyaranyapura

Street ID
W0881, W0576, W0917, W0915, W0919, W0913, W0602, W

Street Name
NA, 1st Crs, 1st Main Rd

Significant Landmark
Deshaband nagar and Surrounding Roads

Segment No.
9/C-W0881/S090728

Total Length (m)
475.92

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	100.38	77.560722	13.059222	77.560874	13.060115	I0344	W0554
2	24.45	77.564160	13.060902	77.564328	13.060755	W0879	DEAD END
3	42.35	77.564296	13.060400	77.564529	13.060706	W0676	DEAD END
4	92.82	77.568978	13.056004	77.569753	13.055649	RAIL TRACK	DEAD END
5	52.30	77.569049	13.056133	77.569279	13.056548	W0602	DEAD END
6	59.00	77.569418	13.055858	77.569673	13.056329	W0604	W0602
7	104.62	77.569179	13.056640	77.570018	13.056173	RAIL TRACK	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements and Asphalting to roads drains and construction of culverts at Deshaband nagar puttanjinappa layout & Krishna temple area in Ward no 09 (

Sanctioned Estimated Amount (Rs.)
4500000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements and Asphalting to roads drains and construction of culverts at Deshaband nagar puttanjinappa layout & Krishna temple area in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
009-16-000009

Work Order No.
BBMP/EE/BTP/WO/105/2016-17

Work Order Date
18/08/2016

Period of Extention
60 DAYS

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #

18/08/2016	17/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M SRIVIVASA MURTHY		0.00

Phone No.	E-Mail ID
9845132243	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		JANARDHAN

Date of Inspection	Remarks
14/09/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0881, W0576, W0917, W0915,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	14/09/2016	14/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0881, W0576, W0917, W0915,

SE	VASU K M	14/09/2016	14/10/2016	COMPLETED
EE	YARAPPA REDDY	14/09/2016	14/10/2016	COMPLETED
AEE	SHIVAKUMAR	14/09/2016	14/10/2016	COMPLETED
AE	JANARDHAN	14/09/2016	14/10/2016	COMPLETED
AE	JANARDHAN	14/09/2016	14/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0881, W0576, W0917, W0915,